Lincoln Avenue Reconstruction

NOVEMBER 19, 2012
SPECIAL TOWN MEETING
ARTICLE 12

The following pictures are

Heading into Saugus from Revere

426
426
428
429
NO STANDING
TOW ZONE
$100 FINE
ENTERING SAUGUS
LINCOLN AVE

Sidewalk Trip Hazard

Worn Asphalt Berm

No Curb / Berm

Sidewalk Trip Hazard

No Curb / Berm

No Curb / Berm

No Curb / Berm

No Curb / Berm

Multiple Layered Previous Repairs

Partial Granite Berm

No Curb / Berm

Sidewalk Trip Hazard

Depressed
Sidewalk


Quasi Berm/Curb

Hybrid Berm/Curb

Lincoln Court

The following pictures are

Headed South from Cliftondale


Badly Cracked Asphalt With
Potholes Developing

Broken Berm / Curb

No Curb / Berm

Broken Sidewalk

Broken Sidewalk

No Curb / Berm


Sunken Utility Connection Trench

Opportunity for Economic Development

No Curb / Berm

No Curb / Berm


Surface Cracks

Uneven Curb / Berm


Pothole

Broken Asphalt


Pothole


Future Potholes
Pothole

Multiple Repairs

Sunken Utility Covers


Potholes / Deterioration

Sidewalk Hazard

Granite Curbs
Welcome to
REVERE
MARTORELLI
Landscaping

Concrete
Sidewalks